FIELD INSPECTION REPORT

Date of	Inspection: o	3-01-21	District: Roktes	
Divisio	n: Rows(w)divi	siony sosoom-1	Length (km): 1.300 F	
Name	f the Road: Ro		To Retichalk.	
Scheme/Programme:		MAINTENANCE Comple		eted
	e No .: MMG	54	Road Id No.:	- Commence
	of the Project:		/Under Maintenance	
71	s a case of:		p gradation/ Maintenance	
SI. No.		Parameters to be checked		Remarks
1.	Pavement			u ⁻³¹ .
a)	Road Junction condition			/S/U
b)	Condition of Surfacing			/\$/U
c)	Riding Quality			S/U
d)	Road Camber			/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Gross Draining	C		
a)	Condition of head walls in Hume pipe culverts including its painting			/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.1	(character):	stoley .		
8)	Status of ATR's	& any others		
				1

Overall Rating

Satisfactory (S)	8"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: MoRogh Porosed Sal

DESIGNATION: JE