MMC, Sy (5°C) FIELD INSPECTION REPORT

Date of Inspection : v.	3-01-20	District: Rohles	
Division: Rwow) drysin, becaran-1		Length (km): 1.70	
Name of the Road: R	anter PHGS&	- road to Balpur Houtin Tolg	
Scheme/Programme:	MAINTENANCE	-	
Package No.:		Road Id No.: Completed.	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	√S/U	
b)	Condition of Surfacing	∕s/U	
c)	Riding Quality	~S/U	
d)	Road Camber	(S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	/Yes/No	
g)	Compaction of flank/slope & raincuts if any	_Yes/No	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	/S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance Elistony		
a)	Status of ATR's & any others	HO	

Overall Rating

Satisfactory (S)	* G W
Satisfactory but requires Improvement (SRI)	7
Unsatisfactory (U)	

(Signature)

NAME: Makest Pooded Sol

DESIGNATION: JE