FIELD INSPECTION REPORT

Date of Inspection: 03-01-24			District: Roktos	
		im, basaram-1	Length (km): 1.020	
Name o	the Road: Jal	aspus 11	Liciproced To Man Ruf	paitha
Scheme	Programme:	MAINTENANCE		
Package	: No.: P	BSPERE	Road Id No.:	
	f the Project:		d/Under Maintenance	
Work is	a case of:		Up gradation/ Maintenance	
SI. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			/s/u
c)	Riding Quality			/ S/U
d)	Road Camber			/ S/U
c)		from defects suc	h as visible cracks, exposed	Yes/No
f)	Contraction Jo	ints provided or not ((CC Pavement)	/Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No	
4	Cross Drainag	Çe.		
a)	Condition of he	cad walls in Hume p	ipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		/S/SRI/U	
3.	Road Furnitw			
a)	Whether sign stones/Pavemen	boards/informatoryant road markings are	/cautionary Board/km & 200m provided and maintained	Yes/No
4.	Chine II a de la	istoky -		
8)	Status of ATR'	s & any others		No

Overall Rating

Satisfactory (S)	"8"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

ModelSel.

(Signature)

NAME: Makest Product Sol

DESIGNATION: JE