FIELD INSPECTION REPORT

		TILLO HAD		
Data of I	nspection: 0	3-01-21.	District: Roklas	
Division	220 12241111	sion, Lososam-1	Length (km): 1.900	
			200d To Amaualiga Bull	eo Tola
	Programme:	MAINTENANCE		
Package			Road Id No.:	pleted
	f the Project:	Ongoing/Combleted	/Under Maintenance	
Work is	a case of:		Jp gradation/ Maintenance	
SI. No.		Parameters to	be checked	Remarks
1.	Pavement	7/1/22		
a)	Road Junction condition			S/U
b)	Condition of Surfacing			- S/U
c)	Riding Quality			S/U
d)	Road Camber			~S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No.
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
70				

Overall Rating

a)

Satisfactory (S)	"s"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Mo

(Signature)

NAME: Mohest PorsadSol

Status of ATR's & any others

DESIGNATION: JE