


FIELD INSPECTION REPORT

Date of Inspection : 4.1.21	District: Aurangabad
Division : Aurangabad	Length (km): 1.40 km
Name of the Road: Ldg - LD53 to Chauriya	
Scheme/Programme: MAINTENANCE	
Package No.: BRD R-750	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	L.H.S. & R.H.S. cracked, Road
a)	Status of A.I.R's & any others	Signage not found. No painting L.H.S. & R.H.S. structure, Bushes found

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


4.1.21
(Signature)

NAME: Babbar Ram
A.C.