

Inspection of Road Under MMGSY (Gon) Road Kit in Chausa Block

FIELD INSPECTION REPORT

Date of Inspection : 24.12.2020	District: Buxar
Division : Rural	Length (km): 1.022 km
Name of the Road: Malavir Ghat Claudesh Path to Handan Tola	
Scheme/Programme: MAINTENANCE MMGSY (Gon) 2019-20	
Package No.: 2019-20	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Grass Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N-A
c)	Condition of railings/slab/approach for Bridges	N-A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mayan Nand Prasad

DESIGNATION: T.E.

(Signature) 24.12.2020