

FIELD INSPECTION REPORT

Date of Inspection :	24-12-2020	District:	Buxar
Division :	Buxar	Length (km):	1.210 km
Name of the Road:	Buxar-Bihar road to Sikanaha Harisaula		
Scheme/Programme:	MAINTENANCE MMUSY (SC)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ongoing		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		✓ S/U
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA	Yes/No
g)	Compaction of flank/slope & raincuts if any	NA	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

M. H. Ansari

NAME:

24-12-2020

(Signature)

R. W. D. Rajpur