work not started.

FIELD INSPECTION REPORT

Date of I	nspection :	03/01/2021	District: No.	lande.	
Division: Har nout			Length (km):	gth (km): 0.550 (2007.	
Name of	the Rond:	L021 4	ने द्वा मिलाह		
Scheme/	Programme:	MAINTENANCE			
Package No.:			Road Id No.:		
Status of the Project:		Onguing/Completed/Under Maintenance			
Work is	a case of:	New Conncetivity/	Jp gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks	
1.	Pavement				
n)	Road Junction	condition		S/U	

SI. No.	No. Parameters to be checked			
1.	Pavement			
n)	Road Junction condition	S/U		
b)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
n	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any Ye			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
基:4. 5-	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not steerted due to land dispute.

(Signature) 01/202/

NAME: RAVI KUMAR

DESIGNATION: fr. Engineer

Scanned with CamScanner