

FIELD INSPECTION REPORT

Inspector: *[Signature]* District: *[Signature]*
 Date: *10/04/2018* Length: *1.0 km*
 (the Road) *200 ft* *1.0 km* *200 ft* *1.0 km*
 Programme: *UNDP/UNICEF*
 Road ID No: *1010121073*
 (the Project) *Improving Connectivity & Infrastructure*
 a part of: *Basic Connectivity & Infrastructure Maintenance*

Parameters to be checked	Remarks
Pavement	☒
Road Junction condition	☒
Condition of Surfacing	☒
Riding Quality	☒
Road Curb	☒
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Construction defects provided or not (CC Pavement)	Yes/No
Condition of Road/Shoulders & drainage if any	Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
Condition of railings/chain approach for Bridges	N/A
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 2km marker/Pavement road markings are provided and maintained	Yes/No
Compliance History	
Status of ATR's & any others	

along: *S*

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
 (Signature)