

(12)

## FIELD INSPECTION REPORT

Date of Inspection :	22-12-2020	District:	Buxar
Division :	Buxar	Length (km):	1.50 km
Name of the Road:	Buxar-Kochas path to Gyan maheshwari fak		
Scheme/Programme:	MAINTENANCE	mmsy (SC)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓	S/U
b)	Condition of Surfacing	✓	S/U
c)	Riding Quality	NA	S/U
d)	Road Camber	✓	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

Mubarak Hussain Ansari.

NAME:

(Signature)

R. W. D. Rajpur