

FIELD INSPECTION REPORT

Date of Inspection :	22-12-2020	District:	Buxar
Division :	Buxar	Length (km):	1.29 Km
Name of the Road:	change main Mahan pu to Saran.		
Scheme/Programme:	MAINTENANCE	mm/sy (GEM)	
Package No.:		Road Id No.:	
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance		
Work is a case of:	<input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance		


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U
c)	Riding Quality	<input checked="" type="checkbox"/> S/U
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<input checked="" type="checkbox"/> S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m <input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

Mubarak Hussain Ansari

NAME:


 22-12-2020
 (Signature)
 Rtd Raipur