

FIELD INSPECTION REPORT

Date of Inspection : 31-12-2020 District: PURNIA
 Division : DHAMDANA Length (km): 0.940 KM
 Name of the Road: Phulwaria Mithai to Phulwaria Mithai
 Scheme/Programme: MAINTENANCE
 Package No.: MM 64 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/
b)	Condition of Surfacing	S/
c)	Riding Quality	S/U
d)	Road Camber	S/
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/UY
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/S/UY
c)	Condition of railings/slab/approach for Bridges	S/S/RY
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Pranav
 31-12-2020
 (Signature)

NAME: PRANAV KUMAR
 (S.I.)