


### FIELD INSPECTION REPORT

Date of Inspection : <u>23-12-20</u>	District: <u>Buxar</u>
Division : <u>Buxar</u>	Length (km): <u>0.900 km</u>
Name of the Road: <u>Kritpura Gobindpur Road to Puliyon village</u>	
Scheme/Programme: <u>MAINTENANCE</u>	
Package No.: <u>01 MG-S-4</u>	Road Id No.:
Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>	
Work is a case of: <u>New Connectivity/Up gradation/ Maintenance</u>	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	<u>S/U</u>
b)	Condition of Surfacing	<u>S/U</u>
c)	Riding Quality	<u>S/U</u>
d)	Road Camber	<u>S/U</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<u>Yes/No</u>
f)	Contraction Joints provided or not (CC Pavement)	<u>Yes/No</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u>
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	<u>S/SRI/U</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u>
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u>
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>Yes/No</u>
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<u>8 S</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

  
 (Signature) 23.12.20

NAME: