

Inspection of Road Under Works by (CC) Road List in Vaughan Block

FIELD INSPECTION REPORT

Date of Inspection: 24.12.2020	Location: Buzar
Division: Buzar	Length (km): 2.205 Km
Name of the Road: Buzar, Vaughan Road to Hargoon main Road	
Scheme/Programme: MAINTENANCE 1996 SY (CC) 2013-20	
Package No.: 3.17.25	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & re-inents if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slabs/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) H. Basu 24.12.2020

NAME: Maya Nand Prasad

DESIGNATION: T.E.