

M. M. - 429 (General)  
**FIELD INSPECTION REPORT**

<b>Date of Inspection :</b> 03-01-21		<b>District:</b> - Raktas
<b>Division :</b> RW D(W) division, Sahasrab-1		<b>Length (km):</b>
<b>Name of the Road:</b> Bagan Jahamabad PNGSY Path To Bhaluadi To B. K. B. N. D. G.		
<b>Scheme/Programme:</b>	MAINTENANCE	
<b>Package No.:</b>	17 PNGSY	<b>Road Id No.:</b> completed
<b>Status of the Project:</b>	Ongoing/Completed/Under Maintenance	
<b>Work is a case of:</b>	New Connectivity/Up gradation/ Maintenance	

  

Sl. No.	Parameters to be checked	Remarks
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	2/0

**Overall Rating :**

<b>Satisfactory (S)</b>	* 3 1/
<b>Satisfactory but requires Improvement (SRI)</b>	
<b>Unsatisfactory (U)</b>	

M. M. - 429  
03-01-21.

(Signature)

**NAME:** Mahesh Prasad Sah

**DESIGNATION:** JE.