

FIELD INSPECTION REPORT

Date of Inspection : 24.12.20		District: Buxar	
Division : R.O.D Buxar		Length (km):	
Name of the Road: Rakasiya Muraspur Road se Dewakali Dhorampur.			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	NA	S/U
b)	Condition of Surfacing	NA	S/U
c)	Riding Quality	NA	S/U
d)	Road Camber	NA	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA	Yes/No
g)	Compaction of flank/slope & raincuts if any	NA	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

[Signature]
24.12.2020
J.C.

(Signature)