

FIELD INSPECTION REPORT

Date of Inspection : 29-12-2020		District: Buxar
Division : RWD, Dumraon		Length (km): 1.550 km
Name of the Road: Raghunathpur Bagen path ke Kaithi Se Nachap Gaon		
Scheme/Programme: MAINTENANCE		MMGSY (SC)
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/S/I
b)	Condition of Surfacing	✓/S/I
c)	Riding Quality	✓/S/I
d)	Road Camber	✓/S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

A Kumar
29/12/2020
JE

[Signature]
29/12/22
(Signature)

NAME:

DESIGNATION: