## FIELD INSPECTION REPORT

Date of Inspection: 03 01 2021			District : Katihar	•
Division: Katihar			Length (Km): 1.000	Km
Name of the Road: Maheshpur school to MuniTolo				
Scheme/Programme: Maintenance (MMGSY-SC)				
Package No.: Road ID No.:				
Status of the Project: Ongoing/Completed/Under Maintenance				ting
Work is a case of: New Connectivity/Up gradation/Maintenance				
SI. No	<u> </u>	Parameters to be Chec	cked	Remarks
1).	Payement			
a)	Road Junction condition			S/U WIP
b)	Condition of Surfacing			S/U WIP
c)	Riding Quality			S/U WII
d)	Road Camber			✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)			✓Yes/No
g)	Compaction of Flank/Slope & Raincuts if any			✓ Yes/No
2).	Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting			✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			✓S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges			s/sri/u N/A
	Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No WIP
4).		lory		e to excel
a)	Status of ATR's &	any others		
Overall Rating : Satisfactory (S)				S
Satisfactory but requires Improvement (SRI)				
		Unsatisfactory (U)		
pcc Parement Completed. GSB216BMGrr3 Completed.				

Name: Dhormendog Kumar Degisnation: J.E (Kursela)

RWD, Works Division, Katihar.