


FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020	District : Bhagalpur	
Division : Bhagalpur	Length (Km) :	
Name of the Road : NH80 Jawahar Mandal (Kamargant) house to Muslim taluqa via Ganesh Singh house		
Scheme / Programme :		
Package No. : MMWSY (GEN)	Road Id No. : 207032/2634	
Status of the Project : Ongoing / Completed / Under Maintenance <input checked="" type="checkbox"/>		
Work is a case of : New Connectivity / Up gradation / Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes / No
g)	Cmpaction of flank/slope & raincuts if any	✓ Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U ✓
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No
Overall Rating		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	

Note: Logo board not paint properly (i) plaster plaster damage (ii) No flank maintain

NAME: Rajkishor Rajah
DESIGNATION: AE

Signature: 
22.12.2020
AE