

# FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 0.936 Km	
Name of the Road : S.H 2 Near A.K. Gopaln College to Rajhangapur Gram			
Scheme / Programme :			
Package No. : M.M.G. 11		Road Id No. : 20703210314	
Status of the Project :   Ongoing / Completed / Under Maintenance			
Work is a case of :   New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S / U	
b)	Condition of Surfacing	✓ S / U	
c)	Riding Quality	✓ S / U	
d)	Road Camber	✓ S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes / No	S
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes / No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	] NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)		

Note : Logo board not painted properly (iv) 1. Km 200m stone not found  
 BT damage in some part (iv) Flank not maintain properly

NAME : Rajkishor Rajak  
 DESIGNATION : A.E

Signature 22.12.2020