

FIELD INSPECTION REPORT

Date of Inspection :		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 3.20 km.	
Name of the Road : Sahjapur Block chowk Diggi to Harjan Tola Dhobi Tola, Pawan Tola			
Scheme / Programme : MMGSY (SC)			
Package No :		Road Id No : 2070 3213023	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	N.A.
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others	No	
Overall Rating			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	S.R.I.	
	Unsatisfactory (U)		

Note :

NAME :

DESIGNATION :

Signature
19/12/20
19/12/2020