FIELD INSPECTION REPORT

Date of Inspection: 03-01-21.			District: Rohtes	
Division: RWD(w) division, logaron -1			Length (km): 1-830 12-14	
Name	of the Road: Cost	of rand for Saraiy	4 Pare To Kali Dondis To 2	Magekan
Scheme/Programme: MAINTENANCI				
Packag		`		ndeted
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is	s a case of:		gradation/ Maintenance	
SI. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			/S/U
c)	Riding Quality			S/U
d)	Road Camber			/S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			/ Yes/No
g)	Compaction of flank/slope & raincuts if any			/Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U

Condition of railings/slab/approach for Bridges

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

a)

Satisfactory (S)	15 12
Satisfactory but requires Improvement (SRI)	0
Unsatisfactory (U)	

ModedCal 03-01-21.

S/SRI/U

Yes/No

NO

(Signature)

NAME: Makest Pooded Sol

Road Furniture

Compliants Highly

Status of ATR's & any others

DESIGNATION: JE