

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan vibhakar
2 Name of Block/Road- Katal Bazar Shyam Bilari Ram keghar to mahuli
primary puth dal.

A For Road

- 1 Damage Location/Chainage 0.0 Km, 0.070 Km, 0.170 Km, 0.270 Km, 0.50 Km
2 Damage Length 0.3463 Km
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works- Brice bnd
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length - 0.3463 Km

B. For Bridge

- 1 Damage Location/Chainage
2 Damage Length
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works-
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length

Signature of JE/ AE/ EE


Signature

(Name of Inspector)

EE

RWD work Division
muzaffarpur G-88 -1

GENERAL ABSTRACT

Name of Road Berai Sham Bihari Ram ke ghar to Muli PMGSY Path Tak

District Muzaffarpur

Block Katra

Division Muzaffarpur East-2

Length of Road (in Km) 0.750 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	20.994
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	20.994
TOTAL COST OF PROJECT IN LACS =		20.994

Say 20-99 lac

[Signature]

JE
RWD

[Signature]

AE
RWD

[Signature]

EE
RWD

*Technically approved for Rs 20-99 lac
(Rupees twenty lac ninety nine thousand only)*

[Signature]

SE

RWD work circle
muzaffarpur