

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- *Gyan vibhakar*
2 Name of Block/Road- *Katwa / Baigra Jalchampur path to Jaguar*
Barf Pokhar Durga mandir

A ☒ For Road

- 1 Damage Location/Chainage *0.020km, 0.240km, 0.500km, 0.600km, 0.300km*
2 Damage Length *- 0.245km*
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works- *Brickbats & Local soil*
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length *0.245km*

B. ☐ For Bridge

- 1 Damage Location/Chainage
2 Damage Length
3 Nature of Damage
4 Details of Restoration Works-
i Material being used in Restoration Works-
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length

Signature of JE/ AE/ EE

[Signature]
12.12.20

Signature

(Name of Inspector)

EE

RWD work division
muzaffarpur cantt - 1

GENERAL ABSTRACT

Name of Road Baigna Lakhanpur Path to Jajuar Bari Pokhar Durga Mandir

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 1.900 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earth Work	1.289
2	Jhama metal	26.444
3	Sand Filling	0.556
4	Sand bag	0.000
5	Bamboo Piles	0.000
6	H.P.	0.477
	GRAND SUB TOTAL	28.766
TOTAL COST OF PROJECT IN LACS =		28.766

say 28.77 lac



JE
RWD




AE
RWD



EE
RWD

Technically approved for Rs 28.77 lac
(Rupees Twenty Eight lac seventy seven thousand only)



SE
RWD WORKCIRCLE
muzaffarpur