

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- *Gyan viphalpur*
2 Name of Block/Road- *Ketola / Ram Bined Singh ke ghar to Patel Chowk Barad*

A For Road

- 1 Damage Location/Chainage *0.100km, 0.120km, 0.150km, 0.400km*
2 Damage Length *— 0.040km*
3 Nature of Damage
4 Details of Restoration Works-

- i Material being used in Restoration Works- *Brick bats & local sand*
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length - *0.040km*

B. For Bridge

- 1 Damage Location/Chainage
2 Damage Length
3 Nature of Damage
4 Details of Restoration Works-

- i Material being used in Restoration Works-
ii Equipments/Tools being used in Restoration Works-
iii Procedure Taken up in Restoration Works-
iv Restored Length

Signature of JE/ AE/ EE

[Signature]
12.12.20
Signature
(Name of Inspector)


EE
RWD WORK DIVISION MUZAFFARPUR
East-1

GENERAL ABSTRACT


Name of Road Ram Binod Singh ke Ghar to Patel Chowk Berai
District Muzaffarpur
Block Katra
Division Muzaffarpur East-2
Length of Road (in Km) 0.690 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	2.649
2	Sand Filling	0.062
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	2.712
TOTAL COST OF PROJECT IN LACS =		2.712


say 2.71 lac


11/11/2020

JE
RWD



11.11.2020

AE
RWD


11/11/20

EE
RWD

Technically approved for Rs. 2.71 lac
(Rupees Two lac seventy one thousand only)


11.11.20
SE

RWD WORK CIRCLE
MUZAFFARPUR