

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan vibhakar
- 2 Name of Block/Road- Katwa/Barsoi PWD road to masjid Hate Huye, Barsoi panchayat
Hate Huye to mullah sah ke ghar and bigali' sat ke ghar tk.

A For Road

- 1 Damage Location/Chainage 0.105 km 0.220 km, 0.290 km, 0.750 km
0.1089 0.281 0.3225 0.775
- 2 Damage Length 0.165 km
- 3 Nature of Damage
- 4 Details of Restoration Works-

- i Material being used in Restoration Works- Brick ball & local sand
- ii Equipments/Tools being used in Restoration Works-
- iii Procedure Taken up in Restoration Works-
- iv Restored Length 0.165 km

B. For Bridge

- 1 Damage Location/Chainage
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works-
 - i Material being used in Restoration Works-
 - ii Equipments/Tools being used in Restoration Works-
 - iii Procedure Taken up in Restoration Works-
 - iv Restored Length

Signature of JE/ AE/ EE

7.12.20
Signature

(Name of Inspector)

EE

RWD work division
muzaffarpur Cant-1

GENERAL ABSTRACT

Name of Road Barari PWD Road to Masjid Hote Huye Barri Pokhar Hote Huye To Gulab sah ke ghar and Bijali
District Roy ke Ghar Tak
Block Muzaffarpur
Division Katra
Length of Road (in Km) Muzaffarpur East-2 0.806 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	57.002
2	Sand Filling	0.745
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	57.747
TOTAL COST OF PROJECT IN LACS =		57.747

say 57.75 lac

[Signature]
25/11/2020

JE
RWD

[Signature]
25.11.2020

AE
RWD

[Signature]
EE
RWD

Technically approved for Rs 57.75 lac
(Rupees fifty seven lac seventy five thousand only)

[Signature]
26.12.20

SE
RWD WORK CIRCLE
MUZAFFARPUR