FIELD INSPECTION REPORT

Date of 1	nspection :	51121	District: Patro		
			Length (km): 005	25	
Name of the Road: SPM ROAD TO NASRINACHAK TOK PATE					
Scheme/	Programme:	MAINTENANCE	HABARD / Ma	inte	new
Package No.:			Road Id No.:		
			Under Maintenance		
Work is a case of: New Connectiv			p gradation/ Maintenance	e	The state of the s
Sl. No.	Parameters to be checked				Remarks
1.	Pavement				
a)	Road Junction condition			Ų	S/U
b)	Condition of Surfacing			y	S/U
e)	Riding Quality			N	S/U
d)	Road Camber			4	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Courface evacual Yes/No				
f)	Contraction Joints provided or not (CC Pavement)			40	Yes/No
g) .	Compaction of flank/slope & raincuts if any Chaineub				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its pa			ainting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3,	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained			200m	Yes/No
4.	Compliance History				
a)	Status of ATR's & any others				NO ATIZ
Overall Rating :					
Satis		Satisfactory (S)	atisfactory (S)		-
			equires Improvement (S	(SRI)	
Unsatisfactory (U)				(J)	

Pushkar Brund Ass H. Engineer

(Signature)

NAME: