## FIELD INSPECTION REPORT

		Unsatisfactory (U)	mes improvement (SXX)	(
Overall Rating : Satisfactory (S)  Satisfactory but requires Improvement (SRI)				1
	n	Satisfactory (S)	•	5
a)	Status of ATR	's & any others		7,0
4).	Compliance History			NU
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Ves/No
3).	Road Furniture			
e)	Condition of Railings/Slab/Approach for Bridges			S/SRI/UNI A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U NA
a)	Condition of Head walls in Hume Pipe Culverts including its painting  •			S/SRI/U
2).	Cross Drainage			
<u> </u>	Compaction of Flank/Slope & Raincuts if any			¥es/No
(i)	Contraction Joints provided or not (CC Pavement)			V Yes/No
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
d)	Road Camber			<b>√</b> S/U
c)	Riding Quality			√S/U
b)	Condition of Surfacing			S/U
a)	Road Junction condition			S/U
Sl. No 1).	Dovoment			
Work is a case of:		Parameters to be Checked		Remarks
Contract of the Contract of th			npleted/Under Maintenance tivity/Up gradation/Maintenance	
Package :	No.:		Road ID No. :	
Scheme/I	Programme:	Maintenance M M	msp(sc)	
Name of	the Road:	_036 to Adh	aura Mushani TNa.	
Division: Katihar Length (Km): 2.243				
Date of Inspection: Du   0   202   District: Katihar			114	

Name: Utan kr Sah.

Degisnation: J. E. RWD, Works Division, Katihar.

Scanned by CamScanner

(Signature)