FIELD INSPECTION REPORT

Date of Inspection: 01/01/2021			District : Katihar	
Division : Katihar			Length (Km):	
Name of	f the Road: As	hok Yadav Kegl	haz to Santhal tolo	
Scheme	/Programme :	Maintenance MM h.s y	(ST)	
Package No.:			Road ID No.:	
Status of the Project : Ongoing/Completed/Unde			r Maintenance	
Work is a case of: New Connectivity/Up gra			on/Maintenance	
	A THE STATE OF THE	Parameters to be Cho		Remarks
	Pavement	A Control of the Cont	100	The Control of the Co
a)		d Junction condition		S/U Parstilly!
b)	Condition of Surfacing			√ 8/U
<u> </u>	Riding Quality			✓ S/U
c) d)	Road Camber			✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)			✓ Yes/No
	Compaction of Flank/Slope & Raincuts if any			✓Yes/No
g)	Cross Drainage			The state of the s
2).	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U
a) b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			s/sri/u N/A
b) c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U N/A
3).	D. O. Riveriday			San et al.
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m			Yes/No
4).	Compliance History			
a)	Status of ATR's & any others			NIO
		G (1 6 - A (6)		
Overall Rating : Satisfactory (S) Satisfactory but requires Improvement (SRI)				SR1
		Satisfactory but requires In	mprovement (SKI)	

Name: PAPPU KUMAR

Unsatisfactory (U)

Degisnation: J・E

RWD, Works Division, Katihar.

Scanned by CamScanner

(Signature)