

FIELD INSPECTION REPORT

Date of Inspection: 17/12/20	District: Nalanda
Division: Biharsahit	Length (km): 1.0 km
Name of the Road: Belwa Khari	Go8anagar Panchayat Bhawan, Nalanda
Scheme/Programme: MAINTENANCE	
Package No.: 4515	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U S
b)	Condition of Surfacing	✓ S/U S
c)	Riding Quality	✓ S/U S
d)	Road Camber	✓ S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature) 17/12/20

NAME: ASHOK KUMAR

DESIGNATION: A.E.