FIELD INSPECTION REPORT

Distrcit: SARAN Date of Inspection: 05.01.2021

Length (km): 2.075 Division: SONPUR

Name of the Road: Mirjapur Sima se Lorik Dom to Karhi Pul PMGSY Sadak tak

Scheme/Programme: MAINTENANCE

Road ID No: Package No:

Status of The Project: MAINTENANCE

Work is a case of: Maintenance

Vork is a case of : Maintenance		Remarks
SI.No	Parameters to be checked	
1	Pavement	S
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S S
f)	Contraction Joints provided or not (CC Pavement)	5
g)	Compaction of Flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe Culverts including its painting	S
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	S
c)	Condition of railings/slab/approach for Bridges	S
3	Raod Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's any others	NO

Overall Rating:

Overall Rating.		
Satisfactory (S)		
Satisfactory but requires Improvement (SRI)	S	
Unsatisfactory (U)		

NAME:- RAJEEV RANJAN KUMAR DESIGNATION: JUNIOR ENGINEER