

# FIELD INSPECTION REPORT

|                                                                        |                        |
|------------------------------------------------------------------------|------------------------|
| Date of Inspection : 05-12-2020                                        | District: Vaishali     |
| Division : Magipur                                                     | Length (km): 1.66      |
| Name of the Road: Daulatpur Rai Vikender College to Chaputa Yadav Tola |                        |
| Scheme/Programme: MAINTENANCE                                          |                        |
| Package No.:                                                           | Road Id No.: Ward - 14 |
| Status of the Project: Ongoing/Completed/Under Maintenance             |                        |
| Work is a case of: New Connectivity/Up gradation/ Maintenance          |                        |

| Sl. No. | Parameters to be checked                                                                                             | Remarks       |
|---------|----------------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | Pavement                                                                                                             |               |
| a)      | Road Junction condition                                                                                              | S/U S         |
| b)      | Condition of Surfacing                                                                                               | S/U S         |
| c)      | Riding Quality                                                                                                       | S/U S         |
| d)      | Road Camber                                                                                                          | S/U S         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No Yes    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No Yes    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No YES NO |
| 2.      | Cross Drainage                                                                                                       |               |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U S     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U S     |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U S     |
| 3.      | Road Furniture                                                                                                       |               |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No        |
|         | Compliance History                                                                                                   |               |
| a)      | Status of ATR's & any others                                                                                         |               |

Overall Rating :

1

SRI

|                                             |  |
|---------------------------------------------|--|
| Satisfactory (S)                            |  |
| Satisfactory but requires Improvement (SRI) |  |
| Unsatisfactory (U)                          |  |

Sanjay  
05.12.20  
ATC

(Signature)

NAME:

DESIGNATION: