

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020	District: West Champaran
Division : Narkatraganj	Length (km):
Name of the Road: Chuhazi sarichari road to Bijwaraya Baroda Basti	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes
f)	Contraction Joints provided or not (CC Pavement)	yes
g)	Compaction of flank/slope & raincuts if any	NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Binod Kumar

DESIGNATION: SE

(Signature) 16.12.20

अभियन्ता
प्राथमिक कार्य विभाग
कार्य अंचल बेतिया