


FIELD INSPECTION REPORT

Date of Inspection : 30.12.2020	District: W. Champaran
Division : Narkatia gand	Length (km): 1.882 km
Name of the Road: L036 to mahmadwa	
Scheme/Programme: MAINTENANCE	
Package No.: BR-37R-477	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	pmhsy
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	8'
b)	Condition of Surfacing	8'
c)	Riding Quality	8'
d)	Road Camber	8'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	8'
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	8'
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	8'
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 30/12/20
 (Signature)

NAME: Chandradeo Prasad
 DESIGNATION: Junior Engineer