

FIELD INSPECTION REPORT

Date of Inspection: 23.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.765
Name of Road : Baban Ghat to Kushwaha talu		
Scheme / Programme: MAINTENANCE		mmbsy (GEN)
Package No:		Road Id No:
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	No
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	U
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridge	1.
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R-5
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

U


Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
<input checked="" type="checkbox"/> Unsatisfactory(U)	

Ramesh Kumar Singh

JF

NAME:

DESIGNATION :


 23.12.2020
 (Signature)