

FIELD INSPECTION REPORT

4/54 (5)

Date of Inspection : 21.12.20.	District: Patna.
Division : (Sampatchak) Patna.	Length (km): 0.700 km
Name of the Road: Soh gimore culvert to Gopalpur chamartoli	Piped tree.
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	U
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	U
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: Supriya Rani

DESIGNATION: Assistant Engineer.
RWD (w) Sub division
Sampatchak, Patna.

Supriya.
21.12.20.
(Signature)