FIELD INSPECTION REPORT

Date of	Inspection :	5//12)	District: Potra	
Division: Masaure Length (ki			Length (km): 2.550	
Name o	f the Road:	OI to Fat	esturia Ramani	bigate
Scheme	Programme:	MAINTENANC	E PMGSY / Mainten	und-1
Package			Road Id Nd.:	
			eted/Under Maintenance	T records
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
SI. No.		Parameter	n to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S 87U
b)	Condition of Surfacing			S/U
c)	Riding Quality			s S/U
d)	Road Camber			S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			· Yes/No
(1)	Contraction Joints provided or not (CC Pavement)			Yes/No
g) -	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ige		Den Jan
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			₩S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
а)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			MOATR
Overall I	Rating :			
		Satisfactory (S		5
		Satisfactory b	ut requires Improvement (\$RI)	-
		Ummaticfantam	w (TI)	The second of the second

Pushkar Prosad Ans H. Erzinen Signature)

NAME: