

FIELD INSPECTION REPORT

Date of Inspection : 17/12/20		District: Nalanda	
Division : Bihar		Length (km): 0.65 km	
Name of the Road: 1064-701 to Baxerhar Road			
Scheme/Programme: MAINTENANCE			
Package No.: PM 4.87		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	S/U	5
b)	Condition of Surfacing	S/U	5
c)	Riding Quality	S/U	5
d)	Road Camber	S/U	5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	yes
g)	Compaction of flank/slope & rineous if any	Yes/No	yes
2. Cross Drainage			
a)	Condition of head walls in trune pipe culverts including its painting	S/SR/U	5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	5
c)	Condition of railings/slab/approach for Bridges	S/SR/U	5
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	yes
4. Compliance History			
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: ASHOK KUMAR

DESIGNATION: D-5

(Signature)