

FIELD INSPECTION REPORT

Inspection: 31-12-20	District: Nalanda
Hill	Length (km): 2.55 km
The Road: L100 Gumbhar Auliyani road to Mahamedpur middle school	
Programme: MAINTENANCE	Mean terminal
Id: PM 634	Road ID No.:
The Project: Ongoing/Completed/Under Maintenance	Under maintenance
Case of: New Connectivity/Upgradation/Maintenance	Maintenance

Parameters to be checked	Remarks
Pavement	
Road Junction condition	S
Condition of Surfacing	S
Binding Quality	S
Road Camber	S
Surface free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No/Yes
Attraction Joints provided or not (CC Pavement)	Yes/No/Yes
Inspection of Bank/slope & raincuts if any	Yes/No/Yes
Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/SRI
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/-
Condition of railings/slab/approach for Bridges	S/SRI/-
Furniture	
Whether sign boards/informatory/cautionary Boards km & 200m & Pavement road markings are provided and maintained	Yes/No
Accident History	
of ATRs & any others	Yes

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

of Karmam Arun

Arun