

FIELD INSPECTION REPORT

Date of Inspection: 31-12-20	Division: P. & S. D.	Length (km): 1.5 km
Name of the Road: Logo to, Kachay gram - In Ladipur	Scheme/Programme: MAINTENANCE	
Package No:	Road ID No:	
Status of the Project: Ongoing/Completed/Under Maintenance	Under maintenance	
Work in case of: New/Improvement/Up gradation/Maintenance	Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road length/condition	S
a)	Condition of Surfacing	S
a)	Riding Quality	S
a)	Road Camber	S
a)	Whether free from defects such as visible cracks, exposed aggregates or case of CC Pavement.	Yes/No
a)	Construction joints provided or not (CC Pavement)	Yes/No
a)	Compaction of subgrade & basecourse if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Stone pipe culverts including its painting	S/SRI/SAT
a)	Condition of Abutment & Wing walls/Slab in RCC culverts	S/SRI/-
a)	Condition of railings/slab approach for Bridges	S/SRI/-
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Boards & 200m. stone's Pavement mark markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

SAT

NAME

Pranali Parmar Arge

31/12/20