## G73NY FIELD INSPECTION REPORT

Date of Inspection :	05.01-21	District: Rohas	
Division: Sas	9m -T	Length (km): 1.40 /cm	
Name of the Road: 4	2011 - Hrel 81	पद से रहें न्यु हमा महत्र किए दोना	
Scheme/Programme:	MAINTENANCE - UTSNY		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Complished History		
a)	Status of ATR's & any others		

## Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ju 31.21

(Signature)

NAME:

**DESIGNATION:**