

FIELD INSPECTION REPORT

Date of Inspection : 05-01-2021		District: Gaya	
Division : Gaya		Length (km): 0.756	
Name of the Road: Khas Bhamra to Matadapur			
Scheme/Programme: MAINTENANCE		Package No.: P-122-689	
Road Id No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		Work is a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - NA	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Road Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U - NA	
c)	Condition of railings/slab/approach for Bridges	S/SR/U - NA	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Overall Rating			
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature: 1.2021
(Signature)

NAME: Chandra Sheela Kumari

DESIGNATION: TE