

FIELD INSPECTION REPORT

Date of Inspection :	16.12.20	District:	Gaya
Division :	Gaya	Length (km):	0.653
Name of the Road:	L109-102 Patchpur Road To Usheri		
Scheme/Programme:	MAINTENANCE		
Package No.:	GR-12R-717	Road Id No.:	PI1454
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SL No.	Parameters to be checked	Remarks
I. Pavement		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SR/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SR/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4. Condition of Road		
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

MANOJ KUMAR

DESIGNATION:

A.C.

Manoj Kumar
16.12.20
(Signature)