

FIELD INSPECTION REPORT

Date of Inspection :	31-12-20	District:	GAYA
Division :	GAYA	Length (km):	1.172 KM
Name of the Road:	TETARIYA ROAD TO BHAGWANPUR		
Scheme/Programme:	MAINTENANCE	PMGSY	
Package No.:	BR12R 959	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No N.A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Drainage History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N. K. Kumar
31.12.20
(Signature)

NAME: MANOJ KUMAR
DESIGNATION: A.E.