## FIELD INSPECTION REPORT

	nspection: 9	31/12/2020	District: Jamui		
Division: Jomui			Langth (km): D = 0		
Name of	the Road: Kha	ing Managhand	ex pwb sord to charge		
		MAINTENANCE	a han sond to charge	au vin	rea
Package			Road Id No.: 20804103	148	
Status of the Project: Ongoing/Complete		Ongoing/Completed/	d/Under Maintenance		
Effection Annual Co.	a case of:	New Connectivity/U	p gradation/ Maintenance		
\$1. No.		Parameters to	ve checked	Remarks	
1	Pavement		The Control of False at		
a)	Road Junction	condition	Market State of State of Contract of Contr	₽\$/U	
b)	Condition of Surfacing				
				JS/U	
c)	Riding Quality			SAU	
d)	Road Camber			ĿS/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
12.	Cross Draina	B THE ASSESSED			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U N	<b>A</b>
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N/	A
3.	Road Farnita	ie Personal			
- <b>a</b> )	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	Compliance History				
a)		's & any others		ND	1

Overall Rating

Satisfactory (S)	9
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: 31)12

3) 12/2020

(Signature) Ar

**DESIGNATION:**