

FIELD INSPECTION REPORT

Date of Inspection :	31.01.2021	District:	VAISHALI
Division :	HAJIPUR	Length (km):	
Name of the Road:	LOR Manura Muchari Tada to Siman chowk (V12)		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-36R-218	Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	SRI

Overall Rating :

NOTE → During Flood in the year 2020, P.C.C. of length 5 mt has been at change 90 mt.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
31.12.2020
(Signature)

NAME: PREM PRAKASH RANJAN

DESIGNATION: AE