

FIELD INSPECTION REPORT

Date of Inspection: 23/12/20	District: East Champaran
Division: Mithari	Length (km): 1.50 K.M.
Name of the Road: 4029 to TAKIA	
Scheme/Programme: MAINTENANCE	PMGSY
Package No.: BR-11R-606	Road Id No.: —
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - N/A -
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - N/A -
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	-N/A-

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Prashant
23/12/20
(Signature)

NAME: *Prashant Sharma*

DESIGNATION: J.E.