06/01/2021 (37) WhatsApp





Division	Date of Inspection: 20-12-20 District: Wastelmann			
Name o	Name of the Road: Length (km): 0.300 km			
Scheme	Programma	MAINTENANC		-
Packago	No.: Do	37R-598.	Road Id No.	
Work in	f the Project:	Ongoing/Comple	eted/Under Maintenance	232
SI. No.	R CBSC OI:	New Connectivit	y/Up gradation/ Maintenance	
		Parameters to be checked Remarks		
1.	Payement			
a)	Road Junction condition			S
b)	Condition of Surfacing			5
c)	Riding Quality			
d)	Road Camber			S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			NA
f)	Contraction Joints provided or not (CC Pavement)			NA
g)	Compaction of flank/slope & raincuts if any			5.
21	Cross Drains	ige		-
a)	THE REAL PROPERTY AND PERSONS ASSESSED.	And the second s	pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			NA
c) .	Condition of railings/slab/approach for Bridges			NA
	Road Furnitu		4	
IC-CALDEDA AND	Whether sign	boards/informato	ry/cautionary Board/km & 200m are provided and maintained	SRI
da Compliance History				
NATIONAL IN	Status of ATR'	- CAMPAGE		SRI
7.	1 3 5	7- 111 - 11		100
verall Ra	ting :	Satisfactory (S)	
		Satisfactory bu	et requires Improvement (SRI)	SRI
		Unsatisfactory	(0)	
	Vista Pa	LAT AP SINGA	(SI	Sind Sind Sind Sind Sind Sind Sind Sind

https://web.whatsapp.com