


FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020		District: W. Champaran
Division : Nalika Hagan		Length (km): 1.6 km
Name of the Road: LO88 - TOI Pandai Chowk TO Maheshpur paschim Tola		
Scheme/Programme: MAINTENANCE		
Package No.: BR-37R-606		Road Id No.: 31808902240
Status of the Project: Ongoing/Completed/Under Maintenance Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


 16/12/2020
 (Signature)

NAME: BIPIN KUMAR

DESIGNATION: J.E.