


FIELD INSPECTION REPORT

Date of Inspection: 23.12.2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 0.300	
Name of Road: MNP Road Sakhami to Kurmitola		
Scheme / Programme: MAINTENANCE	GTSNY	
Package No:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	R.I
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	R.I
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating : S.R.I

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

Ramesh Kumar Singh
J.E


23.12.2020
(Signature)

NAME:
DESIGNATION :